



## MDC/FDC Counter Instructions

LCD display, 00000 – 99999.

Battery: AA.

To reset, press pause followed by reset to clear the current count.

The display is always "on" and, not having a backlight, consumes very little power.

Highest count speed is 20 a second.

If necessary, press the pause button to activate and start counting.